To: Matt Francis (m.francis@erllc.com)[m.francis@erllc.com] From: Way, Steven Mon 9/22/2014 11:40:12 PM Sent: Subject: Gold King Mine - North Forth Crk drainage Matt, I was up at the GK today and things look good. The one thing that will need to happen before the season ends is to open the channel up more where the road crossing is. As configured now, the spring run-off will blow out the road otherwise down below the creek versus running down the channel. It's great right now to drive across. Also, it would be good to talk tomorrow afternoon or Wednesday after I meet with Todd and our management down here. Thanks, Steve Steven Way Federal On-Scene Coordinator **Emergency Response Unit**

Denver, CO 80202

US EPA - Region 8

1595 Wynkoop Street

Office: 303-312-6723